

Project Number: **CM131412**
 Project Descr.: **CM Project for Order R1698919**
 Partition: **Order Partition for R1698919**
 Partition Priority: **Normal**
 Required Condition: **OH**
 Rem. from A/C: **18.Nov.2019**
 Reason for rem.:

Repair Shop: **ULC-KO**
 Customer: **APOC (AIRCRAFT PART-OUT COMPANY EUROPE BV)**
 Performed Dates: **18.Nov.2019 / -**
 Total Qty: **1.0**


Order number: **R1698919**
 Order dates: **18.Nov.2019 / -**
 External Order: **RO190420**
 Created From: **RC0124819**

In Part Data:
 Part Number: **C20195162**
 Serial Number: **30623**
 Description: **MAIN WHEEL**
 Mat. Class: **R**
 Label number: **1371156**
 Mod. Status:

Out Part Data:
 Part Number: **C20195162**
 Serial Number: **30623**
 Description: **MAIN WHEEL**
 Mat. Class: **R**
 Label number: **1372844**
 Mod. Status:

TSN: **Unknown**
 CSN: **Unknown**

CMM Ref. 32 - 47 - 46

Checked by: 

CMM Rev. No. 11

CMM Rev. date 28. AUG. 2019



Order Text

S/N 30623

REQUESTED CONDITION OH

DUAL RELEASE/TCCA

NO TYRES!

Project Text

FINDINGS: REQUESTED CONDITION OVERHAULED

NO TIRE!

ORIGINAL TIRE P/N APR06755 IS DO NOT WORN

REQUEST PARTS:

NAS1611-464. . . .1ks
TRC2. . . .1ks
NAS1602-903. . . .3ks
MS9068-010. . . .3ks
A36007. . . .1ks
TRRG6. . . .3ks
GA30630. . . .3ks
NAS1291C3M. . . .9ks
NAS1149F0332P. . . .9ks

RETURN CONDITION: OVERHAULED + EASA/TCCA

Findings

Repair Text

OVERHAUL AND INSTALLATION OF THE ORIGINAL TIRE

All work Carried Out in Accordance with CMM 32-47-46 Revision No.11, Dated: 28. August 2019,
Unit cleaned, paint striped, NDT inspected, vizual inspected and repainted.
Assembled with Tire p/n APR06755. . . .s/n 9185A426

Failure Confirmation

Status:

Performed Workscopes

Workscopes	Specification	Performed	Inspected	Double Inspected
DISASSEMBLY: Disassembly / demontáž	According to JC LC-32-0060 rev. 1 part VSEOBECNE and part 01 all./ Podle t.p. LC-32-0060 rev.1 části VSEOBECNE a části 01 celý.	BURGRO	N/A	N/A
CLEANING, PAINT STRIPPING: Cleaning/Čištění	According to LC-32-0060 rev. 1 part 02 all. / Podle LC-32-0060 rev.1 části 02 celý.	BURGRO	N/A	N/A
CLEANING, PAINT STRIPPING: Paint striping / odstranění barvy	According to LG-37-2001/ Podle LG37-2001	BURGRO	N/A	N/A
NDT INSPECTION: NDT Inspection - wheel	According to LC-32-0060 rev 1 part 03 step 1). Works required according to Table 1 / Podle t.p. LC-32-0060 rev.1 části 03 kroku 1). Práce předepsané v tabulce 1.	SEDAT	N/A	N/A
NDT INSPECTION: NDT Inspection - tie bolts	According to LC-32-0060 rev. 1 part 03 step 2)C (2). Send tie bolts with corresponding documents to NDT workshop./ Podle t.p. LC-32-0060 rev.1 části 03 kroku 2)C (2). Předejte šrouby s průvodní dokumentací na provedení NDT kontroly.	SEDAT	N/A	N/A